

# IBM LTO-8 Firmware Version MA71 (HH) Release Announcement

March 2021

## Preface

This Product Information Bulletin announces the release of IBM LTO-8 firmware update MA71 for half-height (HH) drives. These updates are intended, among other things, to increase overall reliability, improve tape handling, further reduce any possibility of error, and provide continued enhancements to diagnostic capabilities.

## Models Affected

This firmware affects all IBM LTO-8 HH drives.

## Upgrade Considerations

All systems running code IBM LTO-8 M571 can be upgraded to LTO-8 MA71.



**CAUTION:** To prevent data corruption, verify that all active backup and recovery jobs to the NEO tape library are completed prior to performing the upgrade.

---

## Downgrades

Downgrades are not supported.

## Functional Improvements (Reduce Permanent Errors)

Firmware fixes included with the MA71 HH update:

### General Drive Improvements

- **Prevent drive hang on Write Attribute command:** Drive hung during a write attribute command due to no space left in the CM. Put in function to handle this condition.
- **Allow FORMAT of a cartridge with invalid EOD:** Drive would not allow a format of a cartridge if the EOD was invalid.
- **Improve high speed tape motion handling:** Added high speed tape motion improvements to reduce media damage due to pack slippage.
- **FSC 6601 on READ at BOP:** Due to a corruption of the BOP (beginning of partition) cache, the drive incorrectly failed.
- **Correct FSC and drive panic when write-protected uninitialized cart is inserted:** The FSC was 4101 and this was changed to FSC 2C30.
- **Changed MP 1Ah to be savable:** Changed MP 1AH to be savable so that changes to this mode page would be persistent over power cycles.

- **Change SCD of FSC 53A0/53A1/53A2 from “6” to “5”:** Changed the SCD for the FSCs listed from a drive/media problem (SCD 6) to a drive problem (SCD 5).
- **Drive failed with an FSC 78B5:** Improved the estimated calculation LPOS to more accurately estimate and solve EOT shutdown (78B5).
- **Align the POST B test with the design capacity given in TPC specifications.** FSC effected is 52Ex.
- **Correct FSC and Tape Alert for CRC error on READ:** The drive incorrectly set TA 32 and FSC 6010 on a READ. These should be TA3 and FSC 601D.
- **Improved ERPs to better recover from repositioning perms (FSC 6353).**
- **Drive Panic during a READ:** Drive was not handling DS fragment which spanned a wrap turn.
- **Drive failed a LOCATE with a FSC 78A0:** Drive incorrectly moved tape in the wrong direction due to an incorrect parameter being passed in code.

## Downloads

Firmware update code IBM LTO-8 MA71 (HH) is available for download for supported NEO users. To download IBM LTO firmware, browse to this site:

[https://ftp.overlandtandberg.com/Firmware/Tape\\_Drives/IBM\\_LTO8\\_Drive/](https://ftp.overlandtandberg.com/Firmware/Tape_Drives/IBM_LTO8_Drive/)