

IPMI on QuikStation®

October 2020



CAUTION: Updating the Intelligent Platform Management Interface (IPMI) firmware can render an RDX QuikStation inoperable.

Description

To maintain system security when using the IPMI port, first change the password to prevent any third-party access by them using the default IPMI login and password. However, due to preprogrammed internal interactions between the QuikStation OS and IMPI, do not update IMPI firmware.

Models Affected

This document applies to the QuikStation 4 and QuikStation 8 models.

More Information

For information on RDX^{\otimes} QuikStation appliances and other Overland-Tandberg products, visit our Knowledge Base at:

https://www.overlandtandberg.com/knowledgebase/

Overland-Tandberg 4542 Ruffner Street, Suite 250 San Diego, CA 92111 USA

TEL 1.858.571.5555 FAX 1.858.571.3664



Tandberg Data Feldstraße 81 44141 Dortmund, Germany

TEL +49 231 5436 0 FAX +49 231 5436 111